

# FILM AND GLASS CLEANER



## *FC-II Heptane-based Film and Glass Cleaner*

The use of FC-II will provide clean negatives to insure better results. FC-II is blended with anti-static compounds to repel dust, thereby reducing the opaquing needed to eliminate pinholes. It quickly removes fingerprints, adhesives, smudges and lint from film and all glass surfaces, and will not leave an oily film or streaks. It will not dissolve nor remove water-based opaque.

### **Benefits**

- Will not harm nor break down silver- or diazo-type film base or emulsions
- Will not remove water-based opaque
- Will clean polystyrene film
- Its antistatic feature helps eliminate pinholes caused by dust particles adhering to the vacuum frame surface
- Ideal for use on film, glass-coated lenses and cameras, and in stripping areas and darkrooms
- Quick drying
- Will not leave an oily film or streaks

### **VOC**

5.8 Lbs. per gallon/692 grams per liter

### **Directions**

**For Film** Saturate a soft, lint-free cloth with FC-II. Clean a small portion of the film and wipe it clean. Compare this portion with other areas of the negative to insure that the full opaque covering is still in tact. If so, proceed with cleaning the entire area. It is not recommended to soak negatives in the film cleaner.

**For Glass** Saturate a soft, lint-free cloth with FC-II and use it to clean the glass. Wipe clean.

### **Packaging**

Pail 5 gallons/19 liters

Drum 55 gallons/208 liters

